Classification		RDS3000		RDS5000	
		Before	After	Before	After
Manifold	Exterior				
Changes		1. Improvement of appearance uniformity			
		2. Change material of extruded material → Improve repeatability of TAP fastening			
		3. Step processing of P port part → Prevent a gasket slipping			
		4. Add 2 protrusions on the manifold gasket			
		5. Made by TPC China		<u> </u>	
Gasket	Exterior	669	6.6	000	609
·		1. Add protrusion shape on P-port part → Improve slipping phenomenon			
Changes		Change the direction of the gasket projection     Before change: Valve direction / After change: Manifold direction     Made by TPC China			
Fill Bolt	Exterior		358		358
Changes		Apply sealing liquid to the fill bolt     Made by TPC China			
Packing Box	Exterior				
Changes		1. Change box color and thickness → Prevent damage when moving or loading - Before change: White / 0.5T → After change: Yellow / 1.7T			